


## TRANSFER FOR NYLON FABRICS



SILICONE PAPER

TRANSFER CONDITIONS
TEMPERATURE: 160°C
TIME: 15 SECONDS
PRESSURE: 4 bar
PEEL - OFF: COLD