


TRANSFER FOR WORKING CLOTHES



SILICONE PAPER or POLYESTER

TRANSFER CONDITIONS
TEMPERATURE: 180°C
TIME: 15 SECONDS
PRESSURE: 4 bar
PEEL - OFF: COLD

