


TRANSFER FOR SPORTSWEAR



POLYESTER

TRANSFER CONDITIONS

TEMPERATURE:
180°C

TIME:
15 SECONDS

PRESSURE:
4 bar

PEEL - OFF:
COLD